

MM-017-05

## T-CONNECTORS

### TYPE C



### TYPE E



### TYPE F



T-Connectors are used when a disconnectable bond is needed. T-Connectors consist of a copper plate on which a thread is welded, each plate is retained by two or four braze pins and allows larger (up to 300 mm<sup>2</sup>) cable sizes to be used.

To braze the largest T-Connector, with 4 brazings, it takes no more than 1-2 min including grinding for the grounding and brazing area.



T-förbindningen används då man vill ha en demonterbar anslutning. Den består av en platta i koppar samt en gängad anslutningsdel. Förbindningen pinnlöds sedan mot arbetsmaterialet. Den gängade anslutningsdelen är av antingen mässing eller rostfritt stål.



Die T-Verbindung ist ein Schraubenverband, der direkt an der Schiene montiert wird. Die T-Verbindung besteht aus einer Kupferplatte mit Gewindeanschlußstück. Die Verbindung wird mit Lötstiften festgelötet. Diese Art von Verbindungen wird dann angewandt, wenn ein abnehmbarer Anschluß erwünscht ist.

Part no.	Type	Thread Size	Thread Length	Thread material	Qty/pack.	Rec. braze pin
SAFE 5005	C	M8	18	Brass	100	2 x 10011
SAFE 5007	C	M12	35	Brass	100	2 x 10011
SAFE 50221	F	M16	32	Stainless Steel	50	4 x 10131
SAFE 5032	E	M16	26	Stainless Steel	50	2 x 10131
SAFE 5017	F	M16	26	Stainless Steel	25	4 x 10131
SAFE 502201	E	M16	35	Stainless Steel	25	2 x 10131